



Health & Safety Authority Quarry Managers Briefing

Via Webex 23nd February 2021





- Industry Joint Initiative
- Quarry Risks particularly
 "Vehicles & Pedestrian Safety"
- Approach to Inspections
- Use of Checklist



H.S.A./ICF Initiative



- Quarrying is accepted as an essential service during the COVID Pandemic
- Quarrying continues to operate (to a limited extent) to supply materials to the construction sector
- We need a level of engagement/interaction with Quarry Management to maintain focus on workplace safety
- While difficult, we need to maintain a level of Inspection in the sector

Dates and Times of presentations



Tuesday 23rd Feb – Managers Pre-campaign Briefing (11am – 12 noon)
 (Hosted by ICF/H.S.A.)

Spring Campaign Toolbox Talks – Managers/Supervisors ——Operators/Workers

Week 1


- Tues 2nd March 11am 11.30am Pedestrian Safety Guidance P. Griffin
- Thurs 4th March 11am 11.30am Vehicle Safety G. Murphy

Week 2

- Tues 9th March 11am 11.30am Brake Testing/Lifting Equipment/ Visibility C. Kelly
- Thurs 11th March 11am 11.30am Traffic Management Plan P. Maslin


2019 Campaign Positives



















2019 Campaign Positives


















2019 Campaign Negatives

















Approach to Quarry Inspection



- "Pedestrian and Vehicle Interactions"
- Vehicle Safety/Vehicle Interactions
- Face Management
- Work at Height
- Drilling and Blasting
- Drowning
- Fixed & Mobile Processing Plant
- Maintenance and machinery isolation
- Ancillary Plant Dangers



Preparing a traffic management plan

HEALTH AND SAFETY AUTHORITY

- Site layout is sketched to reflect traffic and pedestrian areas and movement
- Risk assessment done collectively with workers, haulers and supply chain
- Potential Worker and Vehicle collisions identified and means of minimizing risks established
- Detailed risk assessment completed
- Pedestrians removed from work areas as far as possible
- Convex mirrors placed at the blind or no visibility corners
- Site layout traffic plan is developed
- Signage and one-way drive-through system for every vehicle to avoid the need for reversing

- Site induction toolbox talks and kick-off
 meetings to provide information and instruction
 about traffic management to all.
- Information is provided in advance to delivery drivers and subcontractors coming on site.
- Dedicated areas for loading trucks and small loads established
- Speed bumps at entry and exit gates

Management

- Traffic and pedestrian behavior monitored
- Site supervision completes regular audits
- Safety alerts are shared with other sites to learn from near misses

Foynes Site!

Legislation & Guidance

HEALTH AND SAFETY
AUTHORITY

- Safety, Health and Welfare at Work Act 2005
- Safety, Health and Welfare at Work, (Quarry) Regulations 2008
- General Applications Regulations



Pedestrian and Vehicle Interactions

- Dedicated Parking Areas for Visitors/Employees Vehicles
- Pedestrian Routes to be immediately identifiable
- Dedicated small load pick up area
- Segregation of Pedestrians
 & Vehicles at all times
- Hauliers to remain in their Vehicles During loading
- https://vimeo.com/189619601

(Drone - Traffic Management)

https://www.youtube.com/watch?v=xikTo809p_g https://www.youtube.com/watch?v=2kjBg9oWk84



ALTH AND SAFETY AUTHORITY







Location :		Date:			
Quarry Entrance and Office	Yes	No	N/A	Comments	
Is there adequate Signage at Quarry Entrance? (Warning of Vehicle Movements/Speed Limits/Parking areas/Customers & Visitors to report to reception or Office or Weighbridge)					
Are Procedures in place for small load customers? (Trailers etc.)	111111	tttt	*****		
Are Rules Prepared and provided to Customers/Visitors?		cttt	111111		
Are there identified Pedestrian routes with directions from parking areas?		no est estrece son Localistic (Elizabe	· · · · · · · · · · · · · · · · · · ·	111213223333333333333333333333	
Traffic Routes	Hilli				
Is there a Traffic Management Plan?		7515			
Are traffic routes identified and sign-posted?				13137137127121271277777777	
Are roadways well designed with surfaces well maintained?					
Are there speed limits signs?					
Are speed limits enforced?	Hill			TEET TEET TO THE T	
Are rights of way signposted?	TEELER				
Are appropriate one-way systems in use?	Trans.				
Is reversing minimised?	111111			17016161612222222222222222	
Are actions taken to protect pedestrians? (identified routes & segregation)	HIH			1911年1月1日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日日	
Light Vehicles & Service Vehicles				11121/11100/11100 计连续系统	
Are light vehicle movements restricted in the quarry? (Who/When/Where)	HILL			A.C. (1) 以 以 以 动动 动 计 经 经 经 经 经 经 经 经 经 经 经 经 经 经 经 经	
Do Light vehicles have roof mounted flashing amber/hazard lights on?			A. the	担任 以此,年年 经共享	
Are Procedures in place for Light Vehicle drivers to follow? (Rights of way/ Traffic Routes)					
Do Tractors/Fuel Bowsers/Water Bowsers/Road Sweepers have beacons and warning lights?					
Are PTO Shafts adequately guarded?		11313	HIII	11 (12) (12)	

Checklist matches Question Set



Vehicle and Pedestrian Safety Checklist HEALTH AND SAFETY AUTHORITY	2021 Initiative		
Vehicles			
Do vehicles have adequate Reversing and visibility aids?			
Is Brake testing carried out on Loading Shovels and Dumper Trucks?	ATT CALL PRINTS SERVICE THE		
Can tyre inflation take place without endangering persons?			
Is there a policy on "No Children Allowed" in quarry or vehicles?			
Do procedures require drivers to remain in vehicles during loading?	A. C.		
Pedestrians			
Are Pedestrians segregated where possible?	TARREST TO THE PARTY OF THE PAR		
Is appropriate High-Vis PPE provided, used and maintained?	· · · · · · · · · · · · · · · · · · ·		
Are Pedestrian Routes identified and Marked?	以以以及 (1)		
Are vehicles restricted from passing close to Pedestrian Doors at Canteens/Welfare Facilities/Workshops/Offices?			
Are Concave/Convex Mirrors provided at blind spots at exits from offices/workshops/canteen/welfare facilities? etc			
Additional Suggestions;			

Useful Videos



New Traffic Management

http://safequarry.com/BestPracticeView.aspx?kBest Practice=1961&fkActivity=32&fkLocation=7

Traffic Pods for Pedestrians

https://m.youtube.com/watch?v=7Tg42qc6_KY&fea ture=youtu.be

Quarry Traffic Management by Drone

https://vimeo.com/189619601

High Speed Site Deliveries

http://safequarry.com/BestPracticeView.aspx?kBest Practice=2006&fkActivity=32&fkLocation=31

Blue Lights for Tarmacking
http://safequarry.com/BestPracticeView.aspx?kBestPractice=1999&fkActivity=40&fkLocation=10

H.S.A. Quarry Video Playlist

https://www.hsa.ie/eng/Your_Industry/Quarrying/Events_Organisations_Publications/Publications_and_Videos/

Traffic Management Induction



- At Tarmac Ltd, Thrislington
 Quarry, contractors had
 provided feedback that when
 visiting for the first time, they
 had found it extremely difficult
 to navigate around the site
 even after receiving a full
 induction.
- Watch & Identify Improvements
- https://vimeo.com/189619601



http://safequarry.com/BestPracticeView.a spx?kBestPractice=2001&fkActivity=37&f kLocation=3



